

Filtration of screen print fumes

Situation:

A British screen supply company manufactures screen print frames of various sizes. The screen material is fixed on the frame using an adhesive. The adhesive fume was a huge problem in the confined small workshop.



Solution:

The GasCart was the ideal solution for solvent filtration from the adhesive. Being mobile enabled the unit to be used any where. Since the picture, the company has purchased more units.

For more info, please contact: Bob Bruce, Nederman UK
E-mail: bob.bruce@nederman.co.uk