

## Solder fume extraction Blick Communications

### Situation:

Blick manufacture pagers, communication equipment and time recording machines. Solder fume was a health and safety problem. Large production area with static safe (ESD) requirements.



**Solution:** 30 x FX50 mini arms ESD, installed directly to each bench. The fumes are taken through a central ducted system to a MFS filter bank.

**For more info, please contact:** Graeme Gladwinfield, Nederman Ltd.  
**E-mail:** [graeme.gladwinfield@nederman.co.uk](mailto:graeme.gladwinfield@nederman.co.uk)