

## Case Story

---

### Problem:

This well known bakery in the Brussels area has been a Nederman customer for about 10 years. In the nineties, they bought several hose and cable reels.

The bakery contacted us recently to find a solution to phase out their mobile vacuum cleaner in the work-place. The vacuum cleaner was no longer effective; the filters were often clogged, the 1 hp motors were burning out and it provided inadequate capacity while cleaning the ovens.

### Solution:

An E-PAK 150 and 430 ft. of stainless steel pipes and five flap-valves were installed in combination with one 884 vacuum reel.

### Result:

There are no vacuum units occupying the floor space. The hose is neatly collected on the hose reel when not in use. The maintenance is heavily reduced on hoses, filters and motors. The cleaning is now much easier and more efficient.

