

Case Story

Problem:

Arcelik A. S. produces ovens for a variety of applications. These ovens require that insulation material be used during assembly. The insulation material was causing lung and eye irritation among employees and Arcelik A. S. needed a solution to their dust problems.

Solution:

Nederman installed (4) ten ft. 5000 Arms and (2) FilterMax C-25 Filtration Units. The 5000 arms are conveniently placed in a location that can be used by several installers as necessary and when not in use can easily be stored out of the way. This solution efficiently and effectively solved Arcelik's dust problems and provided a safe environment for employees.

