

## Case Story

---

### Problem:

Ford Motor Company operates facilities around the world. At this facility in Turkey numerous automotive parts are produced. There are several CNC machines, all of which generate oil mist, coating the floors, machinery and computers. This oil is dangerous to all employees and quickly deteriorates costly machinery.

### Solution:

Nederman was able to install (4) NOM 11 and (1) NOM 4 filtration unit. The efficient solution satisfied Ford and they are very satisfied with the filtration system. We are currently discussing the installation of several more units in this facility.

