

Aluminium body repair bay at Jaguar in Coventry in UK

Situation: Gut Salmon Ltd, a Jaguar repair workshop, has a special aluminium body repair bay, which must be very clean from surrounding ferro/metal contamination.
The body repair operations include grinding, sanding and welding.



Solution: To prevent contamination from surrounding areas, a 6 m wide and 4 m high power curtain in combination with an 8 m wide and 4 m high combi-curtain on C100-curtain aluminium rail, were selected.
All curtains were delivered in Jaguar's own standard colours, i.e. from bottom to top, green - clear transparent - grey.
The bay can allocate two cars at the same time.
For the extraction, a P160 mobile high vacuum unit was chosen.

For more info, please contact: Keith Bowman, Nederman Ltd., UK
E-mail: keith.bowman@nederman.co.uk