

CASE STUDY

**Kadlec Kovovýroba
Turnov – Czech Republic**

Problem:

This firm make parts of agricultural machines. They restored hall for welding places. They wanted to set up safe workplace for workers.



Solution:

We offered him Filtermax and arm Original. We used automatic dampers for arms.