


Case Story

Exhaust extraction systems in new Honda/Citroen car service in Vilnius

Situation: A new car service facility was build in 2003.



Solution: For car service there were installed 5 pieces of exhaust hose reels 865, with 7.5 m hose and with automatic start/stop switch and 1 piece of fan N24.

Benefits: Good efficiency and healthy air in premises.