

Case Story

Exhaust extraction systems in new Daimler Chrysler car and truck service in Vilnius

Situation: A new car and truck service facility was build in 2003.



Solution: For truck service there were installed 10 pieces of exhaust hose reels 865, 2 pieces of rail 920 for trucks in motion, 1 piece of rail 920 stationary system for transporters and 1 piece for cars. Total quality of fans (N16 and N24) are 10 pieces and 1 piece of N29, 1.5kW.

Benefits: Good efficiency and healthy air in premises.