

Welding fume extraction at Altinyaldiz Ltd. in Turkey

Situation: Altinyaldiz Ltd. is a company producing roof systems. Nine workplaces with full day heavy duty welding creates a lot of welding fume problems. The workshop was very quickly filled with welding smoke all over.



Solution: Eight Nederman Original arms 2m and one 5 m N5000 arm were installed, connected to two central fans. As can be seen the air quality has been significantly clean.

For more info, please contact: Mr. Gokhan Yalinay, Havak Ltd., Turkey
E-mail: gyalinay@havak.com